



INCIDENT INVESTIGATION #184651



2691 Meadows Dr

LOCATION DETAILS

Event Date: 12/24/2019 12:00 AM UTC

Right-of-Way:

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt < 18"

Arrival Date and Time: 12/31/2019 05:01 PM UTC



Distance from Ped to Ped:

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? No

Who Performed Reports: Contractor

Contractor Representative: Billy Seidel

Contractor Representative Phone Number: (605) 431-3559

Personnel On Site:

Vehicles/Equipment Being Used For Repairs:

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type:

Occurred During:

Time Occurred:

DAMAGER

Company Name: Concrete Professionals

Contact: Billy Seidel

Contact Phone: (605) 431-5559

Type of Work: Unknown concrete work

Damage Responder: Russ, Simkins

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Criss

Utility Contact Phone:

Utility Representative: Criss

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Auger

Work Performed: Unknown/Other

Excavator downtime? No

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: Yes

Locator Type: Unknown/Other

Work area white-lined: No

Ticket Number: No locate requested

Date Located:

Located By: ZZ_No Locate Requested

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours:

Customers Affected (approx.): 1

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: No

Offsets were used on hard surfaces: No

Line was on prints: No

At Fault: Unknown/Other

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: No


No Locates on Facility: Yes

Damage Exposed Facility: No

COMMENTS

Assessment Comments: On December 24 the contractor digging without a locate request at 2691 meadows drive in Sturgis South Dakota cut in half the plastic service which was a 3/4 inch MDU plastic gas service with a power auger. 811 was called 911 was not. Gas was not blowing due to a EFV valve Contractor on site thought that his boss had called and locate tickets his boss was on vacation and no locate Was requested.

NEW INCIDENT PHOTOS




Date: 12/31/2019 12:04:22 PM

Latitude: 44.066385

Longitude: -103.141233

Heading: 132 degrees




Date: 12/31/2019 12:04:33 PM

Latitude: 44.066408

Longitude: -103.141249

Heading: 132 degrees




Date: 12/31/2019 12:04:40 PM

Latitude: 44.066408

Longitude: -103.141249

Heading: 173 degrees




Date: 12/31/2019 12:04:44 PM

Latitude: 44.066412

Longitude: -103.141254

Heading: 150 degrees



Date: 12/31/2019 12:04:51 PM

Latitude: 44.066410

Longitude: -103.141252

Heading: 168 degrees