



## INCIDENT INVESTIGATION #188096

---



Mondo St & Anderson Rd

### LOCATION DETAILS

**Event Date:** 03/02/2020 10:15 AM America/Denver

**Right-of-Way:** City Street

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 2.00" Plastic

**Facility part of joint trench:** Yes

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt 18" - 36"

**Arrival Date and Time:** 03/03/2020 11:12 AM America/Denver



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Both

**Contractor Representative:** Tanner Brantley

**Contractor Representative Phone Number:** (605) 431-7540

**Personnel On Site:** 2 supervisors 2 techs

**Vehicles/Equipment Being Used For Repairs:** Mini excavator

**Guards or Barricades On Site:** Yes 4

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** Lind Exco

**Contact:** Tanner Bentley

**Contact Phone:** (605) 431-7540

**Type of Work:** Curb stop repair

**Damage Responder:** Russ, Simkins

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Ralph Schad

**Utility Contact Phone:** (605) 390-8512

**Utility Representative:** Ralph schad

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** Yes

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Water

**Excavator downtime?** Yes

**Downtime hours:** 3

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Contract Locator

**Work area white-lined:** No

**Ticket Number:** 2004450750

**Date Located:**

**Located By:** Russell Simkins

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** No

**Interruption hours:**

**Customers Affected (approx.):** 0

## ROOT CAUSE

**Damage within described dig area:** No

**Damage within legal time of request limit:** No

**Marks destroyed by construction:** No

**Marks destroyed by weather:** No

**Whiskers or flags used:** No

**Offsets were used on hard surfaces:** No

**Line was on prints:** No

**At Fault:** Unknown/Other

**Documentation Issue:** No

**Documentation Issue Comments:** No locates have been called in Since the new 2" plastic gas me was installed going East and West from Anderson road to the end of mondo

**Tolerance Zone:** No

**Marking Standards:** No

**Marking Standards Comments:**

**Locate Requested:** No

**Damage with Tolerance Zone:** No

**No Locates on Facility:** No

**Damage Exposed Facility:** No

## COMMENTS

**Assessment Comments:** On March 3rd Lind Exco hit a newly installed unmapped unlocated Montana Dakota utilities 2" plastic gas main with a excavator no locates have been called in since this gas main Has been installed and gone live. 811 and 911 were notified gas was blowing line was cut almost in two.

# NEW INCIDENT PHOTOS

---



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.021160

Longitude: -103.115453

Heading: 167 degrees



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018251

Longitude: -103.113128

Heading: 10 degrees



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018251

Longitude: -103.113128

Heading: 262 degrees




Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018264

Longitude: -103.113479

Heading: 137 degrees



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018678

Longitude: -103.115511

Heading: 230 degrees



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018264

Longitude: -103.113479

Heading: 78 degrees



Date: 03/03/2020 12:49 PM  
America/Denver

Latitude: 44.018264

Longitude: -103.113479

Heading: 123 degrees