



INCIDENT INVESTIGATION #195156



1625 Lando Lane, Rapid City, SD

LOCATION DETAILS

Event Date: 07/22/2020 11:45 AM America/Denver

Right-of-Way: Private Business

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 07/22/2020 01:19 PM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed: N/A

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs: Both

Contractor Representative: Darwin Heying

Contractor Representative Phone Number: (605) 280-7360

Personnel On Site: 1 super, 2 Techs

Vehicles/Equipment Being Used For Repairs: 2 trucks

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred: 11:45 AM America/Denver

DAMAGER

Company Name: Mossrock Landscaping

Contact: Brian Scott

Contact Phone: (605) 673-1021

Type of Work: Landscaping

Damage Responder: Wade, Mackey

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Darwin Heying

Utility Contact Phone: (605) 280-7360

Utility Representative: Darwin Heying

Utility Rep Tech#: N/A

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Landscaping

Excavator downtime? Yes

Downtime hours: 2

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: Yes

Locator Type: Unknown/Other

Work area white-lined: No

Ticket Number: No locate requested

Date Located:

Located By: <Not Listed>

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours:

Customers Affected (approx.): 1

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: Yes

Offsets were used on hard surfaces: No

Line was on prints: Yes

At Fault: Excavator

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: Yes

No Locates on Facility: No

Damage Exposed Facility: Yes

COMMENTS

Assessment Comments: The Excavator was working without ticket clearing away top soil with a backhoe went too deep and damaged a Montana Dakota Utilities 3/4 inch plastic gas service line. Gas was not blowing due to EFV in the line. The contractor was informed by the MDU Tech to call 811 and report the damage. The contractor was working off of locates for Skull Construction that ELM had located. Mossrock Landscaping did not have a ticket in their name

NEW INCIDENT PHOTOS



Date: 07/22/2020 01:20 PM
America/Denver

Latitude: 44.093089

Longitude: -103.184203

Heading: 316 degrees



Date: 07/22/2020 01:20 PM
America/Denver

Latitude: 44.093084

Longitude: -103.184195

Heading: 19 degrees



Date: 07/22/2020 01:20 PM
America/Denver

Latitude: 44.093084

Longitude: -103.184196

Heading: 125 degrees



Date: 07/22/2020 01:20 PM
America/Denver

Latitude: 44.093083

Longitude: -103.184195

Heading: 120 degrees