



## INCIDENT INVESTIGATION #195550

---



0 Downing St, Rapid City, SD

### LOCATION DETAILS

**Event Date:** 08/12/2020 10:30 AM America/Denver

**Right-of-Way:** City Street

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 3/4" Plastic

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt 18" - 36"

**Arrival Date and Time:** 08/12/2020 02:47 PM America/Denver



**Distance from Ped to Ped:** 3ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** Yes

**Who Performed Repairs:** Both

**Contractor Representative:** Mike Dimond

**Contractor Representative Phone Number:** (605) 209-5340

**Personnel On Site:** 2 techs

**Vehicles/Equipment Being Used For Repairs:** 2 pickups, hand tools

**Guards or Barricades On Site:** No

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** JMD Excavating

**Contact:** Mike Dimond

**Contact Phone:** (605) 209-5340

**Type of Work:** Street

**Damage Responder:** Jeremy, Konst

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Ralph Schad

**Utility Contact Phone:** (605) 390-8512

**Utility Representative:** Ralph

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Road Work

**Excavator downtime?** Yes

**Downtime hours:** 2

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Contract Locator

**Work area white-lined:** No

**Ticket Number:** No locate request

**Date Located:**

**Located By:**

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:** 2

**Customers Affected (approx.):** 1

## ROOT CAUSE

**Damage within described dig area:** No

**Damage within legal time of request limit:** No

**Marks destroyed by construction:** No

**Marks destroyed by weather:** No

**Whiskers or flags used:** No

**Offsets were used on hard surfaces:** No

**Line was on prints:** Yes

**At Fault:** Excavator

**Documentation Issue:** No

**Documentation Issue Comments:**

**Tolerance Zone:** No

**Marking Standards:** No

**Marking Standards Comments:**

**Locate Requested:** No

**Damage with Tolerance Zone:** No

**No Locates on Facility:** Yes

**Damage Exposed Facility:** No

## COMMENTS

**Assessment Comments:** The contractor had a ticket for working on Woodlawn they did not have a locate request for Downing street. The contractor hit a Montana Dakota utilities 3/4" plastic gas service with a track hoe gas was not blowing due to EFV and 811 was notified. Mike dimond didn't realize that the ticket does not cover downing street....he will call a ticket in today to have a legal ticket to dig where he is digging now. This damage Occured over 10 feet away from the ROW. The ticket he is digging on was called in 7/11/20 for Woodlawn St only. The only markings in the area at all are across the street from the damage from a previous locate that were on the sidewalk where this line crosses the street towards the point to where it was damaged.

# NEW INCIDENT PHOTOS



Ticket: 2022579807.0 Timestamp:8/12/2020 12:21:50 PM

Date: 08/18/2020 09:07 AM  
America/Denver

Latitude:

Longitude:

Heading:



Ticket: 2022579807.0 Timestamp:8/12/2020 12:22:07 PM

Date: 08/18/2020 09:07 AM  
America/Denver

Latitude:

Longitude:

Heading:



Date: 08/18/2020 09:07 AM  
America/Denver

Latitude:

Longitude:

Heading: