



INCIDENT INVESTIGATION #198433



5723 Harper Ct, Rapid City , SD

LOCATION DETAILS

Event Date: 10/06/2020 11:41 AM America/Denver

Right-of-Way: Public-other

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 0.75" Gas

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time:



Distance from Ped to Ped: 3ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs: Both

Contractor Representative: Cory Jobgen

Contractor Representative Phone Number: (605) 685-8911

Personnel On Site: 1 service tech

Vehicles/Equipment Being Used For Repairs: 1 truck/hand tools

Guards or Barricades On Site: fire dept on site

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred: 11:41 AM America/Denver

DAMAGER

Company Name: Concrete Vision

Contact: Cory Jobgen

Contact Phone: (605) 685-8911

Type of Work: Electrical trench

Damage Responder: Kevin, Keune

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Allen Weinand

Utility Contact Phone: (605) 390-8516

Utility Representative: Allen Weinand

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Electric

Excavator downtime? Yes

Downtime hours: 2

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type: Unknown/Other

Work area white-lined: No

Ticket Number: No ticket

Date Located:

Located By: no locate request

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours: 2

Customers Affected (approx.): 1

ROOT CAUSE

Root Cause:

COMMENTS

Assessment Comments: On October 06, 2020 the contractor was digging with a Mini excavator without a locate request and damaged the Montana Dakota utilities 3/4 inch plastic gas service causing it to leak gas. 911 was notified 811 was notified. There were some faded markings from a past unknown locate that were accurate on site but this contractor does not have a locate request

NEW INCIDENT PHOTOS



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.028240

Longitude: -103.268263

Heading: 249 degrees




Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.027975

Longitude: -103.268416

Heading: 337 degrees



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.027976

Longitude: -103.268410

Heading: 311 degrees



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.028112

Longitude: -103.268444

Heading: 354 degrees



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.027982

Longitude: -103.268410

Heading: 329 degrees



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.028132

Longitude: -103.268446

Heading: 335 degrees



Date: 10/06/2020 12:42 PM
America/Denver

Latitude: 44.028132

Longitude: -103.268446

Heading: 345 degrees



Date: 10/06/2020 12:43 PM
America/Denver

Latitude: 44.028125

Longitude: -103.268380

Heading: 319 degrees