



## INCIDENT INVESTIGATION #198513

---



1710 St Joe St / Jackson Blvd, Spearfish, SD

### LOCATION DETAILS

**Event Date:** 10/09/2020 04:20 PM America/Denver

**Right-of-Way:** Private Land

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 0.75" Gas

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt > 36"

**Arrival Date and Time:** 10/12/2020 05:30 PM America/Denver



**Distance from Ped to Ped:** 20ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Jerry Robinson

**Contractor Representative Phone Number:** (605) 641-4826

**Personnel On Site:** Contractor

**Vehicles/Equipment Being Used For Repairs:**

**Guards or Barricades On Site:**

**Facilities Replaced or Repaired:** Replaced

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** Robinson Builders

**Contact:** Jerry Robinson

**Contact Phone:** (605) 641-4826

**Type of Work:** Excavation for underground drains

**Damage Responder:** Jerred, Conway

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Derek Austin

**Utility Contact Phone:** (605) 580-5245

**Utility Representative:** Derek Austin

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Drainage

**Excavator downtime?** No

**Downtime hours:** 0

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** No

**Locator Type:** Unknown/Other

**Work area white-lined:** No

**Ticket Number:**

**Date Located:**

**Located By:** no locate request

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** No

**Interruption hours:** 0

**Customers Affected (approx.):** 0

## ROOT CAUSE

**Root Cause:** No Locates on Facility

## COMMENTS

**Assessment Comments:** At approximately 4:20 PM mountain time, contractor was digging drainage trench with mini excavator and hit a MDU 3/4" plastic gas service line. the house is unoccupied, gas was not blowing. MDU representative had already been on site and determined immediate repair was not necessary by the time I arrived. The line is to be replaced at a future date. 811 was notified. No locate ticket requested .

# NEW INCIDENT PHOTOS



Date:  
Latitude: 44.501052  
Longitude: -103.869836  
Heading: 191 degrees



Date:  
Latitude: 44.500963  
Longitude: -103.869745  
Heading: 25 degrees



Date:

Latitude: 44.500962

Longitude: -103.869743

Heading: 307 degrees