

INCIDENT INVESTIGATION #198537



3715 Hills View, Spearfish, SD

LOCATION DETAILS

Event Date: 10/12/2020 12:10 PM America/Denver

Right-of-Way: Unknown/Other

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt < 18"

Arrival Date and Time: 10/12/2020 01:30 PM America/Denver



Distance from Ped to Ped: Oft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs: Utility Company

Contractor Representative: KEITH STUEN

Contractor Representative Phone Number: (605) 639-0338

Personnel On Site: One MDU tech

Vehicles/Equipment Being Used For Repairs: 1 truck, hand tools

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred: 12:10 PM America/Denver

DAMAGER

Company Name: Andy Coil Construction

Contact: KEITH STUEN

Contact Phone: (605) 639-0338

Type of Work: Grading

Damage Responder: Jessica, Myers

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Bruce Sprynczynatyk

Utility Contact Phone: (605) 641-1541

Utility Representative: Todd Schmidt

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Grader/Scraper

Work Performed: Grading

Excavator downtime? Yes

Downtime hours: 3

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type: Facility Owner

Work area white-lined: No

Ticket Number:

Date Located: 10/16/2020 02:58 PM America/Denver

Located By: ZZ_No Locate Requested

INTERRUPTION AND RESTORATION

Event cause Interruption: No

Interruption hours:

Customers Affected (approx.):

ROOT CAUSE

Root Cause: No Locates on Facility

COMMENTS

Assessment Comments: Got called at 1:18 for a gas damage at 3715 Hillsveiw Rd. MDU tech was on sight fixing the line when ELM showed up. Gas was not blowing. 911 was not called but 811 was. No locate ticket. Contractor was not on sight when locator showed up. Information was exchanged via MDU tech And ticket info.

NEW INCIDENT PHOTOS



Date: 10/12/2020 01:46 PM

America/Denver

Latitude: 44.513420

Longitude: -103.925087

Heading: 248 degrees



Date: 10/12/2020 01:46 PM

America/Denver

Latitude: 44.513446

Longitude: -103.925108

Heading: 328 degrees