



INCIDENT INVESTIGATION #202106



5808 Eastside Dr, Blackhawk, SD

LOCATION DETAILS

Event Date: 11/30/2020 03:21 PM America/Denver

Right-of-Way: Private Land

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 0.50" Plastic

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 11/30/2020 04:30 PM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed: 0

Repairs Taking Place Upon Arrival? No

Who Performed Repairs: Utility Company

Contractor Representative: Gerrit Solseth

Contractor Representative Phone Number: (605) 484-4880

Personnel On Site: 1 MDU tech and contractor

Vehicles/Equipment Being Used For Repairs: 1 truck / hand tools

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred:

DAMAGER

Company Name: Solseth Excavation

Contact: Gerrit Solseth

Contact Phone: (605) 484-4880

Type of Work: Septic system install

Damage Responder: Russ, Simkins

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Sandi Kile

Utility Contact Phone: (605) 390-8509

Utility Representative: Sandi Kile

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Sewer

Excavator downtime? Yes

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type:

Work area white-lined: No

Ticket Number:

Date Located:

Located By: No locate request

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours:

Customers Affected (approx.): 1


ROOT CAUSE

Root Cause: No notification made to One-Call Center / 811

COMMENTS

Assessment Comments: On November 30th the contractor using a Mini Excavator dug into and cut in half the half inch MDU plastic service gas was not blowing the contractor pinched off the line 811 and 911 were not notified.

NEW INCIDENT PHOTOS



Date: 11/30/2020 04:43 PM
America/Denver

Latitude: 44.141047

Longitude: -103.307725

Heading: 206 degrees



Date: 11/30/2020 04:43 PM
America/Denver

Latitude: 44.141061

Longitude: -103.307724

Heading: 174 degrees