

From: locates@sd811.com
Sent: Tuesday, July 3, 2018 12:01 PM
To: sodbustersinc@midconetwork.com
Subject: Locate Message

To update or view a map of the dig location click [here](#) to go to the South Dakota 811 Portal Site.

Want to **process your own tickets** and **receive your ticket number immediately**? Contact our [Remote Apps](#) department for a quick training. Click [here](#) to view a short video explaining the process.

South Dakota 811 Locate Request

Ticket Number:	1818485002	Old Ticket:	
Source:	Portal Ticket	Date:	7/3/2018 12:00:34 PM
Type:	Normal	Update By:	7/25/2018 12:00:00 PM
Seq Num:	3	Expires On:	7/27/2018 12:00:00 PM

Company Information

Excavator:	SOD BUSTERS	Type:	Excavator
Address:	46919 CODY ST # 200	Contact:	Mike Brown
City, St, Zip:	TEA, SD 57064	Contact Phone:	(605) 498-1066
Phone:	(605) 498-1066	Alt Phone:	(605) 498-1066
Fax:		Caller:	DEB HELMKE
Caller Email:	sodbustersinc@midconetwork.com	Caller Phone:	(605) 498-1066
Contact Email:	sodbustersinc@midconetwork.com		

Work Information

State:	SD	Work Date:	7/6/2018 12:00:00 PM
County:	LINCOLN	Done For:	duration
Place:	SIOUX FALLS	Duration:	1 month
Address:	0 S Bounty PI	Explosives::	No
Intersection:	69th	R.O.W.:	No
Nature of Work:	install irrigation	Tunnel/Bore:	Yes
Meet Requested:	No	Meet Date/Time:	
TRSQ:		Depth:	2 feet

Driving Directions

69th to Tanner then Bounty place North side road

Remarks

Work Date: 7/6/2018 11:15:00 AM 5900-5908 front, sides, rear home, entire property

Members

<u>Code</u>	<u>Name</u>	<u>Manually Added</u>
LCR	Lincoln County Rural Water System Inc.	False

LIN	Southeastern Electric Cooperative Inc.	False
LN1	Southeastern Electric Cooperative Inc *HP*	False
M01	Midamerican Energy Company Inc.	False
MCI	Mci	False
N04	Xcel Energy	False
PWS	Vast Broadband	False
SFA	City Of Sioux Falls	False
SFC	Midcontinent Communications	False
USS	Sprint Nextel	False
UW3	CTLQL-CenturyLink	False

Work Location Bounding Box

Latitude:	43.489319	Longitude:	-96.697751
Second Latitude:	43.492635	Second Longitude:	-96.690112

HP - A high profile facility is in the area and a meet may be required. The operator may also require to be present when excavating. Please refer to Administrative Rule #20:25:03:10.02.

In the future you can submit your tickets quick and easy online at the [South Dakota 811 Portal Site](#).