**Complaint filed on behalf of or by:** Midcontinent Communications

**Contact Person:** Patrick J. Mastel

**Phone** (605) 271-0594

Name or Company Name Midcontinent Communications

3901 North Louise Avenue
Street Address or PO Box
Sioux Falls, South Dakota 57107

**United States** 

Email pat.mastel@midco.com

**Date** Jan 23, 2020

Name of excavator / facility operator: Sod Busters Inc. and B Green

**Phone** (605) 498-1066

Name or Company Name Sod Busters Inc. and B Green

Street Address or PO Box 46919 Cody Trail
Tea, South Dakota 57064

**United States** 

Is this party aware of your

allegations?

Yes

#### Provide detail including whom you spoke with:

Unknown

#### ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:

Violation of 49-7A et. seq., including 49-7A-5 - Notification of excavation not done; and 49-7A-12 - Notification of damaging facilities.

# Other information to support your position:

No locates were done.

Street Address / location of alleged violation: 5906 S. Bounty Pl

**City** Sioux Falls

**State** SD

**Date of alleged violation:** Jul 12, 2018

**Time of alleged violation:** 12:00 PM

## **Describe your allegation:**

Sod Busters and B Green did not do, and admitted not doing, locates prior to doing underground sprinkler repair. Midco's cable was cut.

Do you believe the alleged violat	ion
to be intentional?	

Not Sure

## Why or why not?

Midco does not believe the violation was intentional but Sod Busters and B Green did not do a locate prior to digging at the addresses shown.

Was a locate requested from SD One Call?	No
Did the excavator wait until the start date / time on the ticket before commencing excavation?	No
Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?	No
Were buried facilities exposed by hand or non-invasive equipment prior to excavation?	No
Were facilities marked?	No
Was the marking complete prior to the start time on the ticket?	No
Did the excavator pre-mark with white paint?	No
Was the facility marked accurately (within 18 inches)?	No
Did the excavator use reasonable care to maintain locate marks for the life of project?	No
Type of facility involved:	internet cable

Operator of facility (if known):	Midcontinent Communications	
Operator address (Street or PO Box):	3901 North Louise Avenue Sioux Falls, South Dakota 57107 United States	
Operator Phone	(605) 271-0594	
Depth of Cover (If unsure put N/A)	N/A	
Pressure: (If none, write none)	None	
Voltage: (If none, write none)	None	
# of cable pairs: (If none, write none)	None	
Was the facility damaged?	Yes	
If yes, provide detail and an estimate of damage: Midco's cable was cut. Damage amount \$372.75.		
Were damages on public right of way or private property?	Private	
Was anyone injured as a result of facility damage?	No	
Were there fatalities?	No	
Was operator service affected?	Yes	
If yes, provide detail (how many customers for how long): One customer for 12-24 hours.		
Was the one-call notification center immediately notified of the damage, dislocation, or disturbance?	No	
If No, why not? unknown.		
Was the operator of the facility immediately notified of the damage, dislocation, or disturbance?	Yes	

Was there an escape of any flammable, toxic, or corrosive gas or No liquid?

Please provide a Fire Department or Emergency Services incident report, if available

Not Availiable

## **Attachment Information**

File names should not include symbols. Example:(\$, &, \*, %.) etc.