



## INCIDENT INVESTIGATION #193296

---



Sheridan Lake Rd, Rapid City, SD

### LOCATION DETAILS

**Event Date:** 06/05/2020 08:31 AM undefined

**Right-of-Way:** State Highway

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 0.75" Gas

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Blacktop < 18"

**Arrival Date and Time:** 06/05/2020 10:23 AM undefined



**Distance from Ped to Ped:**

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Jonathon Fish

**Contractor Representative Phone Number:** (701) 282-4971

**Personnel On Site:** Darwin and Henry

**Vehicles/Equipment Being Used For Repairs:** 2 construction trucks one Mini excavator service tuck

**Guards or Barricades On Site:** No

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** Industrial Builders

**Contact:** Johnathan Fish

**Contact Phone:** (701) 282-4971

**Type of Work:** Milling road

**Damage Responder:** Kevin, Keune

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Darwin

**Utility Contact Phone:** (605) 280-7360

**Utility Representative:** Darwin

**Utility Rep Tech#:** Darwin

**Utility Rep. Present on Arrival:** Yes

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Milling Equipment

**Work Performed:** Milling

**Excavator downtime?** Yes

**Downtime hours:** 3

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** No

**Locator Type:** Unknown/Other

**Work area white-lined:** No

**Ticket Number:** No locate requested

**Date Located:** 05/20/2020 12:55 PM undefined

**Located By:** Kevin Keune

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:** 3

**Customers Affected (approx.):** 7

## ROOT CAUSE

**Damage within described dig area:** No

**Damage within legal time of request limit:** No

**Marks destroyed by construction:** No

**Marks destroyed by weather:** No

**Whiskers or flags used:** No

**Offsets were used on hard surfaces:** No

**Line was on prints:** Yes

**At Fault:** Excavator

**Documentation Issue:** Yes

**Documentation Issue Comments:**

**Tolerance Zone:** No

**Marking Standards:** No

**Marking Standards Comments:**

**Locate Requested:** No

**Damage with Tolerance Zone:** No

**No Locates on Facility:** No

**Damage Exposed Facility:** No

## COMMENTS

**Assessment Comments:** On June 5th the contractor Industrial Builders was milling the road at Sheridan Lake road working without a locate request in their name. the contractor that actually has the locate called in is Ostedal Construction. Industrial builders was running a milling machine when they hit the Montana Dakota utilities 3/4 inch plastic service. The locate marks were clearly accurate from the locates performed for Ostedal Construction. Gas was blowing, 811 and 911 were both notified.

# INCIDENT AND SURVEY COMPARISON PHOTOS

## SURVEY PHOTO



Date: 05/20/2020 05:54 PM undefined

Latitude: 44.008889

Longitude: -103.322500

Heading: 34 degrees

## INCIDENT COMPARISON PHOTO



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009590

Longitude: -103.322964

Heading: 259 degrees



# NEW INCIDENT PHOTOS



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009563

Longitude: -103.322979

Heading: 260 degrees



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009563

Longitude: -103.322979

Heading: 139 degrees





Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009508

Longitude: -103.322940

Heading: 267 degrees



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009508

Longitude: -103.322940

Heading: 166 degrees





Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009505

Longitude: -103.322935

Heading: 87 degrees



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009505

Longitude: -103.322935

Heading: 86 degrees





Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009508

Longitude: -103.322936

Heading: 62 degrees



Date: 06/05/2020 10:23 AM undefined

Latitude: 44.009676

Longitude: -103.322562

Heading: 121 degrees