To update or view a map of the dig location click <u>here</u> to go to the South Dakota 811 Portal Site.

### South Dakota 811 Locate Request

Ticket Number:	2014220547	Old Ticket:	
Source:	Voice	Date:	5/21/2020 4:00:29 PM
Туре:	Damage	Update By:	6/9/2020 5:00:00 PM
Seq Num:	1	Expires On:	6/11/2020 5:00:00 PM

# **Company Information**

Excavator:	BTD ENTERPRISE	Туре:	Excavator
Address:	PO Box 2652	Contact:	Nick Emery
City, St, Zip:	Rapid City, SD 57709	Contact Phone:	(605) 791-0470
Phone:	(605) 791-0470	Alt Phone:	(605) 484-2120
Fax:		Caller:	Nick Emery
Caller Email:	BTD.OFFICE@BTDENTERPRISE.COM	Caller Phone:	(605) 791-0470
Contact Email:	BTD.OFFICE@BTDENTERPRISE.COM		

## Work Information

State:	SD	Work Date:	5/21/2020 5:00:00 PM
County:	PENNINGTON	Done For:	State Engineer
Place:	RAPID CITY	Duration:	1 month
Address:	3305 W South St	Explosives::	No
Intersection:	Soo San Dr	R.O.W.:	No
Nature of Work:	DAMAGED GAS LINE	Tunnel/Bore:	No
Meet Requested:	No	Meet Date/Time:	
TRSQ:		Depth:	8 feet

# **Driving Directions**

Remarks

RCL:2012707411- DAMAGE CUT GAS LINE- CREW IS EN ROUTE- CUST W/OUT SERVICE- GAS IS NOT LEAKING OR BLOWING AND LINE IS VISIBLE- LINE IS CUT ON THE BACK SIDE OF BLDG A Utilities must respond within 2 hours M-F and within 4 hours after working hours.

#### Members

<u>Code</u>	Name	<u>Manually</u> <u>Added</u>
BH1	Black Hills Power and Light Company	False
MT3	Montana-Dakota Utilities Company	False
RCC	City Of Rapid City	False
SDT	Sdn Communications Llc	False
TC1	Midcontinent Communications	False
UW1	CTLQL-CenturyLink	False
WID	Vast Broadband	False

# Work Location Bounding Box

Latitude:	44.07721	Longitude:	-103.274713
Second Latitude:	44.078535	Second Longitude:	-103.272079

In the future you can submit your tickets quick and easy online at the South Dakota 811 Portal Site.

Total Control Panel			<u>Login</u>
To: <u>btd.office@btdenterprise.com</u>	Message Score: 50	High (60): Pass	
From: <u>locates@sd811.com</u>	My Spam Blocking Level: Medium	Medium (75): Pass	
		Low (90): Pass	
	Block this sender		
	Block sd811.com		

This message was delivered because the content filter score did not exceed your filter level.