

This is a copy of the picture Nick from Prunty construction sent to the insurance company United Fire.

No date

No sense of direction or depth

No landmarks

Note the size of the cable.

It appears they are measuring a "red" marking flag and a piece of sod with an orange mark on it which both appears to have fallen in a backhoe trench.

I feel this picture has no credibility. As admitted by Ann Landerfield (adjuster) we clearly have to different sites.



tear out cable



locate line



locate line 24" off must be within 18"

