



INCIDENT INVESTIGATION #195864



20989 Maitland Rd, Deadwood, SD

LOCATION DETAILS

Event Date: 08/29/2020 04:51 PM America/Denver

Right-of-Way: Private Land

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 1" Steel

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 08/29/2020 04:51 PM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? No

Who Performed Repairs: Utility Company

Contractor Representative: Scott Anderson

Contractor Representative Phone Number: (605) 520-0787

Personnel On Site: 2 techs

Vehicles/Equipment Being Used For Repairs: 2 trucks, trailer, backhoe

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type: Temporary

Occurred During: After Hours

Time Occurred: 12:30 PM America/Denver

DAMAGER

Company Name: F16 Services

Contact: Scott Anderson

Contact Phone: (605) 520-0787

Type of Work: Septic Tank

Damage Responder: Kenneth, Kauffman

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Mark Knodel

Utility Contact Phone:

Utility Representative: Steve

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Sewer

Excavator downtime? No

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type:

Work area white-lined: No

Ticket Number:

Date Located:

Located By: No locate requested

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours:

Customers Affected (approx.): 1

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: No

Offsets were used on hard surfaces: No

Line was on prints: Yes

At Fault: Excavator

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: No

No Locates on Facility: Yes

Damage Exposed Facility: No

COMMENTS

Assessment Comments: On August 29th the contractor F16 Services hit a 1" steel gas service with a backhoe while doing septic work. They did not have a locate request. gas was blowing. 911 was not notified 811 was notified MDU came and temporarily repaired the line until The contractor finishes the work they are doing then they will come back and permanently fix the line.

NEW INCIDENT PHOTOS



Date: 08/29/2020 04:28 PM
America/Denver

Latitude: 44.370890

Longitude: -103.760546

Heading: 251 degrees



Date: 08/29/2020 04:30 PM
America/Denver

Latitude: 44.370890

Longitude: -103.760546

Heading: 260 degrees




Date: 08/29/2020 04:50 PM
America/Denver

Latitude: 44.371105

Longitude: -103.760821

Heading: 207 degrees



Date: 08/29/2020 04:50 PM
America/Denver

Latitude: 44.371117

Longitude: -103.760710

Heading: 276 degrees