



INCIDENT INVESTIGATION #198595



6767 E Elmwood, Black Hawk, SD

LOCATION DETAILS

Event Date: 10/15/2020 12:45 PM America/Denver

Right-of-Way: Unknown/Other

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 10/15/2020 01:45 PM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs:

Contractor Representative: Sandy

Contractor Representative Phone Number: (605) 390-8539

Personnel On Site: 1 service tech

Vehicles/Equipment Being Used For Repairs: 1 vehicle

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred: 10:51 AM America/Denver

DAMAGER

Company Name: All About Exteriors

Contact: Randy oaks

Contact Phone: (605) 209-8615

Type of Work: Building a shed

Damage Responder: Erik, Smith

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Sandy

Utility Contact Phone: (605) 390-8539

Utility Representative:

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Bldg. Construction

Excavator downtime? Yes

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: Yes

Locator Type: Contract Locator

Work area white-lined: No

Ticket Number:

Date Located: 10/23/2020 10:41 AM America/Denver

Located By: ZZ_No Locate Requested

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours:1

Customers Affected (approx.): 1

ROOT CAUSE

Root Cause: Root Cause not listed above (comment required)

COMMENTS

Assessment Comments: A damage occurred at 12:44 pm at 6767 Elmwood Drive in Blackhawk, SD. The contractor, All About Exteriors, hit the service for the home while digging a foundation using a mini excavator. They DID NOT CALL IN A LOCATE ticket and are at fault in this incident. Gas Blowing, 811 and 911 were notified.

NEW INCIDENT PHOTOS



Date: 10/15/2020 02:22 PM America/Denver

Latitude: 44.149070

Longitude: -103.301961

Heading: 169 degrees



Date: 10/15/2020 02:22 PM America/Denver

Latitude: 44.149070

Longitude: -103.301961

Heading: 226 degrees




Date: 10/15/2020 02:23 PM America/Denver

Latitude: 44.149235

Longitude: -103.301816

Heading: 49 degrees



Date: 10/15/2020 02:32 PM America/Denver

Latitude: 44.149197

Longitude: -103.301921

Heading: 260 degrees