

South Dakota One Call Notification Board
PO Box 187
Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

Complaint filed on behalf of or by:	Montana Dakota Utilities
Contact Person:	Marcus Christensen
Phone	(605) 355-4035
Name or Company Name	Montana Dakota Utilities
Street Address or PO Box	PO Box 1060 Rapid City, South Dakota 57709 United States
Email	marcus.christensen@mdu.com
Date	Nov 06, 2020
Name of excavator / facility operator:	ROBERT KNOWLES
Phone	(605) 342-3787
Name or Company Name	RCS Construction
Street Address or PO Box	1314 Fountain Plaza Drive Rapid City, South Dakota 57702 United States
Email	evan@rcsconst.com
Is this party aware of your allegations?	No

ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:
49-7A-8. Location of underground facilities--Marking.

An operator shall, upon receipt of the notice, advise the excavator of the location of underground facilities in the proposed excavation area by marking the location of the facilities with stakes, flags, paint, or other clearly identifiable marking within eighteen inches horizontally from the exterior sides of the underground facilities. The board shall promulgate rules, pursuant to chapter 1-26, to establish the response time for operators to mark the underground facilities. The response time shall be no later than forty-eight hours after the receipt of the notice, excluding Saturdays, Sundays, and legal holidays of the state or the excavation start time provided by the excavator, whichever is later. The response time may be less than forty-eight hours for emergency or subsequent inquiries to the original locate request and may be longer than forty-eight hours for nonexcavation requests. Excavators shall maintain a minimum horizontal clearance of eighteen inches between a marked underground facility and the cutting edge of any mechanical equipment. If excavation is required within eighteen inches,

horizontally, the excavator shall expose the facility with hand tools or noninvasive methods approved pursuant to rule and shall protect and support the facility prior to further excavation with mechanical equipment.

Other information to support your position:

Contractor hit a 2 gas main while digging what appears to be a trench with a mini excavator. Contractor had valid locate at the time of damage. It appears marks were covered up by there spoil pile from the trench. Pot holing to verify the location of the gas line would of aided in preventing the damage. Gas was blowing. 911 and 811 were notified.

Street Address / location of alleged violation: 30 Adams St

City Deadwood

State SD

Date of alleged violation: Oct 28, 2020

Time of alleged violation: 03:00 PM

Describe your allegation:

Contractor hit a 2 gas main while digging what appears to be a trench with a mini excavator. Contractor had valid locate at the time of damage. It appears marks were covered up by there spoil pile from the trench. Pot holing to verify the location of the gas line would of aided in preventing the damage. Gas was blowing. 911 and 811 were notified.

Do you believe the alleged violation to be intentional? No

Was a locate requested from SD One Call? Yes

Locate ticket #: 2029025013

Start date on ticket: Oct 20, 2020

Start time on ticket: 08:15 AM

Did the excavator wait until the start date / time on the ticket before commencing excavation? Yes

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment? No

Explain

While digging with there excavator the hit a 2in gas main causing it to blow.

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?	No
Were facilities marked?	Yes
Was the marking complete prior to the start time on the ticket?	Yes
Did the excavator pre-mark with white paint?	No
Was the facility marked accurately (within 18 inches)?	Yes
Did the excavator use reasonable care to maintain locate marks for the life of project?	No
Type of facility involved:	2" (P) Gas Main
Operator of facility (if known):	Montana Dakota Utilities
Operator address (Street or PO Box):	PO Box 1060 Rapid City, South Dakota 57709 United States
Operator Phone	(605) 355-4035
Depth of Cover (If unsure put N/A)	~18"-24"
Pressure: (If none, write none)	50psig
Voltage: (If none, write none)	none
# of cable pairs: (If none, write none)	none
Was the facility damaged?	Yes
If yes, provide detail and an estimate of damage:	2" poly gas main \$1000

Were damages on public right of way or private property? Public

Was anyone injured as a result of facility damage? No

Were there fatalities? No

Was operator service affected? Yes

If yes, provide detail (how many customers for how long):
3 hours and 16 customers

Was the one-call notification center immediately notified of the damage, dislocation, or disturbance? Yes

Was the operator of the facility immediately notified of the damage, dislocation, or disturbance? Yes

Was there an escape of any flammable, toxic, or corrosive gas or liquid? Yes and 911 was contacted by an Excavator

Please provide a Fire Department or Emergency Services incident report, if available Not Available

Attachment Information

File names should not include symbols. Example:(\$, &, *, % .) etc.