South Dakota One Call Notification Board PO Box 187 Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing responses to South Dakota One Call Complaints. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination.

COMPLAINT DOCKET NUMBER:	OC20-085
Reply filed on behalf of (company name):	RCS Construction, Inc.
Contact Person:	RC Scull
Phone	(605) 342-3787
Name or Company Name:	RCS Construction
Street Address or PO Box	PO Box 9337 Rapid City, South Dakota 57709 United States
Email	rc@rcsconst.com
Date	Nov 25, 2020
Were you previously aware of these allegations?	No
Do you believe the statutes listed (if any) by the complainant were violated?	No
Do you dispute the alleged violation of SD One Call statute or rule occurred?	Yes

If yes, what specifically do you dispute?

RCS disputes complaint OC20-085.

We acknowledge that we hit the 2" poly gas line; however, after exposing the steel gas line by hand we thought we were in the clear. In our past experience, it is not uncommon to find 2" poly lines inside steel lines in Lead, SD. If records showed that a steel line had been abandoned, a new poly line had been installed, and then this information had been shared with us we would have continued potholing by hand until we found the poly line.

Do you dispute the complainant's statements regarding the intentional or No unintentional nature of the alleged violation? Yes

If yes, please provide the ticket number and a copy of the locate ticket 2029025013. See attached.

Locate ticket #	2029025013
Start date on ticket:	Oct 16, 2020
Start time on ticket:	08:09 AM
Did excavation begin before the start date / time on the ticket?	No
Was a minimum horizontal clearance of 18 inches maintained between a marked facility and mechanical equipment?	Yes
Were buried facilities exposed by hand or non- invasive equipment prior to excavation?	Yes
Were facilities marked?	Yes
Was the marking complete prior to the start time on the ticket?	Yes
Was the excavation site pre-marked with white paint?	No
Was the facility marked accurately (within 18 inches)?	Yes
Was there reasonable care to maintain locate marks for the life of project?	Yes
Did the complainant correctly describe the type of facility involved?	Yes

Provide detail:

The gas main was located correctly by ELM. The problem was the steel main (not knowing it was abandoned) was above the gas main. RCS crews pot holed and found the steel main and believed we found the correct gas main. It is not uncommon to find two inch poly lines inside old steel gas lines in Lead, SD. We believe our crews did everything correctly and the complaint should be rejected. See attached pictures.

Did the complainant correctly describe the damages that resulted from the alleged violation?

No

Provide detail:

Pot holing was completed and the steel line was confirmed. RCS did not know it was abandoned. It is our recommendation for future that 811 come up with a way for the facility providers to notify the contractors/excavators what type of material their active line is.

Was the one-call notification center immediately notified of the damage, dislocation, or disturbance?	Yes
Please provide a copy of the Damage Ticket See attached.	
Was the operator of the facility immediately notified of the damage, dislocation, or disturbance?	Yes
Was there an escape of any flammable, toxic, or corrosive gas or liquid?	Yes and 911 was contacted by an Excavator
Did the complainant correctly describe the damages that resulted from the alleged violation?	Yes
Were damages on public right of way or private property?	Public
Did complainant correctly describe how operator service was affected?	Yes
Provide detail: 3 hours 16 customers	

Was anyone injured as a result of facility damage?	No	
Were there fatalities?	No	
Other information regarding injuries or damages:		

N/A

Describe your plans and procedures to ensure compliance with SD One Call statutes and rules:

See attached.

Has a complaint been filed against you in the past for Yes SD One Call violations?

If yes, when was it filed? Sep 22, 2020

Please provide any additional information to support your position:

See attached pictures showing steel line and new poly line in close proximity to each other. RCS did everything correctly. We had an active locate ticket and we pot holed and found a steel line (not knowing it was abandoned). We feel MDU or 811 should come up with a system to notify the excavators on what type of material the active line is.

Attachment Information

File names should not include symbols. Example:(\$, &, *, %) etc.