



## INCIDENT INVESTIGATION #201747

---



23608 Wilderness Canyon, Rapid City, SD

### LOCATION DETAILS

**Event Date:** 10/30/2020 12:31 PM America/Denver

**Right-of-Way:** County Road

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 3/4" Plastic

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt 18" - 36"

**Arrival Date and Time:** 10/30/2020 01:06 PM America/Denver



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** Yes

**Who Performed Repairs:** Both

**Contractor Representative:** Jason Gibbons

**Contractor Representative Phone Number:** (605) 929-6888

**Personnel On Site:** 1 MDU service tech ,2 Construction crews

**Vehicles/Equipment Being Used For Repairs:** 2 trucks and mini excavator

**Guards or Barricades On Site:** Yes the fire department

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** CSI

**Contact:** Jason Gibbons

**Contact Phone:** (605) 929-6688

**Type of Work:** Install cable TV

**Damage Responder:** Kevin, Keune

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Casey Smith

**Utility Contact Phone:** (605) 390-8513

**Utility Representative:** Casey Smith

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Drainage

**Excavator downtime?** Yes

**Downtime hours:** 2

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Unknown/Other

**Work area white-lined:** No

**Ticket Number:**

**Date Located:**

**Located By:** ZZ\_No Locate Requested

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:** 2

**Customers Affected (approx.):** 1

## ROOT CAUSE


**Root Cause:** No notification made to One-Call Center / 811

## COMMENTS

**Assessment Comments:** Contractor didn't have locates . They do not have a proper locate ticket in the area that were working in , they also did not have a proper damage locate ticket it does not state that the gas line was hit and the damage was on Wilderness Canyon at 23606 not.Silver Fox Spur. gas was blowing 911 and 811 were notified. The contractor using a Mini excavator was digging up existing conduits to try and locate a conduit for their cable TV in an area they do not have locates for where they hit the 3/4 inch Montana Dakota utilities plastic gas service.

# NEW INCIDENT PHOTOS

---



Date: 10/30/2020 01:55 PM America/Denver

Latitude: 43.984181

Longitude: -103.320683

Heading: 338 degrees



Date: 10/30/2020 01:55 PM America/Denver

Latitude: 43.984181

Longitude: -103.320683

Heading: 350 degrees

