

# **INCIDENT INVESTIGATION #201977**



## 23590 Wilderness Canyon Rd, Rapid City, SD

## **LOCATION DETAILS**

Event Date: 11/16/2020 03:15 PM America/Denver Right-of-Way: County Road

## AFFECTED FACILITY

Near Miss: No Type of Operation Affected: Gas Line Size and Type: 3/4" Plastic Facility part of joint trench: No Asphalt or concrete removed: No Damage Surface Type and Depth: Dirt 18" - 36" Arrival Date and Time: 11/17/2020 03:38 PM America/Denver



Distance from Ped to Ped: Oft Dimensions of Asphalt or Concrete Removed: Repairs Taking Place Upon Arrival? Yes Who Performed Repairs: Both Contractor Representative: Jacob Hoffmam Contractor Representative Phone Number: (605) 929-6688 Personnel On Site: 1 supervisor 1forman 3 construction 1 services tech Vehicles/Equipment Being Used For Repairs: 5 trucks 1 mini Guards or Barricades On Site: 911 notified fire dept on site Facilities Replaced or Repaired: Repaired Replacement Type: Permanant Occurred During: Business Hours Time Occurred: 3:15 PM America/Denver

#### DAMAGER

Company Name: Jacob Hoffman Contact: Jacob Hoffman Contact Phone: (605) 929-6688 Type of Work: Cable TV install Damage Responder: Kevin, Keune

#### UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities Utility Contact Name: Doyle Heying Utility Contact Phone: (605) 390-8517 Utility Representative: Doyle Heying Utility Rep Tech#: Utility Rep. Present on Arrival: Yes

#### **EXCAVATION INFORMATION**

Excavator Type: Contractor Excavation Equipment: Backhoe/Trackhoe Work Performed: Cable Television Excavator downtime? Yes Downtime hours: No Downtime cost: No

#### NOTIFICATION AND LOCATING

One Call Center notified: No Locator Type: Unknown/Other Work area white-lined: No Ticket Number: Date Located: Located By:

#### **INTERRUPTION AND RESTORATION**

Event cause Interruption: Yes Interruption hours: Customers Affected (approx.): 1

### **ROOT CAUSE**

Root Cause: No notification made to One-Call Center / 811

### COMMENTS

**Assessment Comments:** The Contractors working without a locate request they dug through a Montana Dakota utilities gas service cutting it in half, gas was blowing, 911 and 811 were both notified.

## **NEW INCIDENT PHOTOS**



Date: 11/17/2020 03:44 PM America/Denver

Latitude: 43.986235 Longitude: -103.316781 Heading: 357 degrees



Date: 11/17/2020 03:44 PM America/Denver

Latitude: 43.986248 Longitude: -103.316776 Heading: 23 degrees



#### Date: 11/17/2020 03:45 PM America/Denver

Latitude: 43.986279 Longitude: -103.316779 Heading: 196 degrees



Date: 11/17/2020 03:52 PM America/Denver

Latitude: 43.986268 Longitude: -103.316868 Heading: 9 degrees



Date: 11/17/2020 03:52 PM America/Denver

Latitude: 43.986291 Longitude: -103.316834 Heading: 24 degrees



Date: 11/17/2020 03:52 PM America/Denver

Latitude: 43.986294 Longitude: -103.316828 Heading: 40 degrees