



INCIDENT INVESTIGATION #185839



0 N Valley & N Creek

LOCATION DETAILS

Event Date: 01/28/2020 12:00 AM UTC

Right-of-Way:

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 4" Plastic

Facility part of joint trench: Yes

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 01/28/2020 06:42 PM UTC



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? No

Who Performed Reports: Both

Contractor Representative: Dennis Turman

Contractor Representative Phone Number: (605) 484-3624

Personnel On Site: 1 super and 3 tech's for MDU

Vehicles/Equipment Being Used For Repairs: 3 trucks 1 trailer and 1 mini excavator

Guards or Barricades On Site:

Facilities Replaced or Repaired: Repaired

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred:

DAMAGER

Company Name: Dream Construction

Contact: Dennis Turman

Contact Phone: (605) 484-3624

Type of Work: Repair Water main valves

Damage Responder: Kevin, Keune

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Ralph Schad

Utility Contact Phone: (605) 390-8512

Utility Representative: Ralph Schad

Utility Rep Tech#: 6947

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Water

Excavator downtime? Yes

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: Yes

Locator Type: Contract Locator

Work area white-lined: No

Ticket Number: 2001547608

Date Located:

Located By: Keune, Kevin

INTERRUPTION AND RESTORATION

Event cause Interruption: No

Interruption hours:

Customers Affected (approx.): 0

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: No

Offsets were used on hard surfaces: No

Line was on prints: No

At Fault: Unknown/Other

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: No

No Locates on Facility: Yes

Damage Exposed Facility: No

COMMENTS

Assessment Comments: On 1/28/2020 a contractor working for dream construction damage a unmarked 4" plastic MDU gas main on North Valley drive in Rapid City South Dakota using a Mini excavator gas was blowing. the contractor does not have a ticket under dream constructions name they were working off a ticket using Kaski As the name which was the contractor name being used working here previously. the contractor said they did not have a ticket underneath their name and it was calling in all new tickets with their name on them. 811 and 911 were both called The contractor hit the line with a Mini excavator.

NEW INCIDENT PHOTOS



Date: 1/28/2020 11:33:42 AM

Latitude: 44.093638

Longitude: -103.180409

Heading: 7 degrees




Date: 1/28/2020 11:33:52 AM

Latitude: 44.093638

Longitude: -103.180409

Heading: 33 degrees



Date: 1/28/2020 11:42:55 AM

Latitude: 44.093546

Longitude: -103.179442

Heading: 29 degrees



Date: 1/28/2020 11:43:47 AM

Latitude: 44.093452

Longitude: -103.179080

Heading: 18 degrees



Date: 1/28/2020 11:43:53 AM

Latitude: 44.093452

Longitude: -103.179084

Heading: 360 degrees



Date: 1/28/2020 11:44:02 AM

Latitude: 44.093446

Longitude: -103.179073

Heading: 171 degrees



Date: 1/28/2020 11:44:13 AM

Latitude: 44.093436

Longitude: -103.179097

Heading: 151 degrees