

Picture taken by Tammy on 8-22-2019 when Prunty construction hit the cable. It is very hard to see but there is an orange paint mark between the two men in alignment with the backhoe bucket.

There are clear landmarks; Tammy's driveway and the church across the street.

Also you can see muddy boots as well as mud on the one guys jeans. In Nicks picture there is no mud on the guys hands down in the trench.

Plus the man in Pruntys picture is wearing a hard hat and no vest, in Tammy's picture he is wearing a cap and vest.

Tammy's picture also has no date on it but it does show the date taken on her phone.

