



INCIDENT INVESTIGATION #195564



671 South St, Whitewood, SD

LOCATION DETAILS

Event Date: 08/12/2020 03:00 PM America/Denver

Right-of-Way: Private Land

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: Yes

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 08/12/2020 04:56 PM America/Denver



Distance from Ped to Ped: 103ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs: Utility Company

Contractor Representative: Jesse Lawson

Contractor Representative Phone Number: (605) 641-8383

Personnel On Site: Jesse lawson, Bruce from MDU

Vehicles/Equipment Being Used For Repairs: 1 truck ,Hand tools

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Replaced

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred:

DAMAGER

Company Name: Riley Homes

Contact: Rodger Riley

Contact Phone: (605) 641-0960

Type of Work: Adding utilities

Damage Responder: Jessica, Myers

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Bruce Sprynczynatyk

Utility Contact Phone: (605) 641-1541

Utility Representative: Bruce S

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Electric

Excavator downtime? Yes

Downtime hours: 2

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type: Unknown/Other

Work area white-lined: No

Ticket Number: No locate requested

Date Located:

Located By: <Not Listed>

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours: 2

Customers Affected (approx.): 1

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: No

Offsets were used on hard surfaces: No

Line was on prints: Yes

At Fault: Excavator

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: No

No Locates on Facility: Yes

Damage Exposed Facility: No

COMMENTS

Assessment Comments: On August 12th at 3:00 MDU called and informed me that there was a gas line hit in White Wood SD. Using a backhoe the contractor had hit the MDU 3/4 inch plastic gas service line for 671 south st while trenching to add utilities for 673 south st. The contractor does not have a locate requested. Gas was not blowing do to a EFV. 811 was notified, 911 was not. Gas was just leaking when MDU tech arrived.

NEW INCIDENT PHOTOS



Date: 08/12/2020 04:56 PM
America/Denver

Latitude: 44.457473

Longitude: -103.631907

Heading: 317 degrees