

South Dakota One Call Notification Board
PO Box 187
Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

Complaint filed on behalf of or by:	Montana Dakota Utilities
Contact Person:	Marcus Christensen
Phone	(605) 355-4035
Name or Company Name	Montana Dakota Utilities
Street Address or PO Box	PO Box 1060 Rapid City, South Dakota 57709 United States
Email	marcus.christensen@mdu.com
Date	Sep 10, 2020
Name of excavator / facility operator:	Wayne May
Phone	(605) 343-5162
Name or Company Name	Rapid Construction LLC
Street Address or PO Box	2783 Plant St Rapid City, South Dakota 57702 United States
Email	Waynerconst@rushmore.com
Is this party aware of your allegations?	No

ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:
49-7A-8. Location of underground facilities--Marking.

An operator shall, upon receipt of the notice, advise the excavator of the location of underground facilities in the proposed excavation area by marking the location of the facilities with stakes, flags, paint, or other clearly identifiable marking within eighteen inches horizontally from the exterior sides of the underground facilities. The board shall promulgate rules, pursuant to chapter 1-26, to establish the response time for operators to mark the underground facilities. The response time shall be no later than forty-eight hours after the receipt of the notice, excluding Saturdays, Sundays, and legal holidays of the state or the excavation start time provided by the excavator, whichever is later. The response time may be less than forty-eight hours for emergency or subsequent inquiries to the original locate request and may be longer than forty-eight hours for nonexcavation requests. Excavators shall maintain a minimum horizontal clearance of eighteen inches between a marked underground facility and the cutting edge of any mechanical equipment. If excavation is required within eighteen inches,

horizontally, the excavator shall expose the facility with hand tools or noninvasive methods approved pursuant to rule and shall protect and support the facility prior to further excavation with mechanical equipment.

Street Address / location of alleged violation:	W Elm and Juniper St
City	Blackhawk
State	South Dakota
Date of alleged violation:	Sep 04, 2020
Time of alleged violation:	01:30 PM
Describe your allegation:	Contractor was working on installing a water main when they hit the gas line. Contractor had a valid locate ticket. Contractor didn't use caution when digging with the excavator and may not have potholed the gas prior to. The contractor also entered the gas to stop it from blowing.
Do you believe the alleged violation to be intentional?	No
Was a locate requested from SD One Call?	Yes
Locate ticket #:	2024694475
Start date on ticket:	Sep 04, 2020
Start time on ticket:	08:00 AM
Did the excavator wait until the start date / time on the ticket before commencing excavation?	Yes
Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?	No
Explain	Contractor hit the gas line with there digging equipment tearing the gas line in half.
Were buried facilities exposed by hand or non-invasive equipment prior to excavation?	No
Were facilities marked?	Yes

Was the marking complete prior to the start time on the ticket?	Yes
Did the excavator pre-mark with white paint?	No
Was the facility marked accurately (within 18 inches)?	Yes
Did the excavator use reasonable care to maintain locate marks for the life of project?	No
Type of facility involved:	1/2" (P) Gas Line
Operator of facility (if known):	Montana Dakota Utilities
Operator address (Street or PO Box):	PO Box 1060 Rapid City, South Dakota 57709 United States
Operator Phone	(605) 355-4035
Depth of Cover (If unsure put N/A)	~18"-24"
Pressure: (If none, write none)	50psig
Voltage: (If none, write none)	none
# of cable pairs: (If none, write none)	none
Was the facility damaged?	Yes
If yes, provide detail and an estimate of damage:	Gas service line - \$800
Were damages on public right of way or private property?	Public
Was anyone injured as a result of facility damage?	No
Were there fatalities?	No

Was operator service affected? Yes

If yes, provide detail (how many customers for how long):

1 hour - 1 customer

Was the one-call notification center immediately notified of the damage, dislocation, or disturbance? Yes

Was the operator of the facility immediately notified of the damage, dislocation, or disturbance? Yes

Was there an escape of any flammable, toxic, or corrosive gas or liquid? Yes and 911 was not called

Please provide a Fire Department or Emergency Services incident report, if available Not Available

Attachment Information

File names should not include symbols. Example:(\$, &, *, %, .) etc.