

**South Dakota One Call Notification Board**  
**PO Box 187**  
**Rapid City, SD 57709**

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

<b>Complaint filed on behalf of or by:</b>	Askland Ditching
<b>Contact Person:</b>	Matt Askland
<b>Phone</b>	(605) 209-3306
<b>Name or Company Name</b>	Askland ditching
<b>Street Address or PO Box</b>	Po box 951 Rapid city, South Dakota 57701 United States
<b>Email</b>	<a href="mailto:Asklandditching@yahoo.com">Asklandditching@yahoo.com</a>
<b>Date</b>	Sep 14, 2020
<b>Name of excavator / facility operator:</b>	Mdu
<b>Phone</b>	(605) 342-0160
<b>Name or Company Name</b>	Mdu
<b>Street Address or PO Box</b>	718 Steele ave Rapid city, South Dakota 57701 United States
<b>Email</b>	<a href="mailto:Mdu@mdu.com">Mdu@mdu.com</a>
<b>Is this party aware of your allegations?</b>	No
<b>Provide detail including whom you spoke with:</b>	No locates
<b>ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:</b>	No gas locates
<b>Other information to support your position:</b>	No gas locates
<b>Street Address / location of alleged violation:</b>	3402 ivy ave
<b>City</b>	Rapid city

<b>State</b>	South Dakota
<b>Date of alleged violation:</b>	Sep 14, 2020
<b>Time of alleged violation:</b>	08:00 AM
<b>Describe your allegation:</b> Call inn locates Mdu did not respond or mark	
<b>Do you believe the alleged violation to be intentional?</b>	No
<b>Why or why not?</b> Idk I'm not the locator	
<b>Was a locate requested from SD One Call?</b>	Yes
<b>Locate ticket #:</b>	2025398888
<b>Start date on ticket:</b>	Sep 14, 2020
<b>Start time on ticket:</b>	08:00 AM
<b>Did the excavator wait until the start date / time on the ticket before commencing excavation?</b>	Yes
<b>Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?</b>	Yes
<b>Were buried facilities exposed by hand or non-invasive equipment prior to excavation?</b>	NA
<b>Were facilities marked?</b>	No
<b>Was the marking complete prior to the start time on the ticket?</b>	NA
<b>Did the excavator pre-mark with white paint?</b>	NA

<b>Was the facility marked accurately (within 18 inches)?</b>	NA
<b>Did the excavator use reasonable care to maintain locate marks for the life of project?</b>	NA
<b>Type of facility involved:</b>	Gas
<b>Operator of facility (if known):</b>	Mdu
<b>Operator address (Street or PO Box):</b>	718 Steele ave Rapid city, South Dakota 57701 United States
<b>Operator Phone</b>	(605) 342-0160
<b>Depth of Cover (If unsure put N/A)</b>	0
<b>Pressure: (If none, write none)</b>	0
<b>Voltage: (If none, write none)</b>	0
<b># of cable pairs: (If none, write none)</b>	0
<b>Was the facility damaged?</b>	No
<b>Were damages on public right of way or private property?</b>	NA
<b>Was anyone injured as a result of facility damage?</b>	NA
<b>Were there fatalities?</b>	No
<b>Was operator service affected?</b>	No
<b>Was the one-call notification center immediately notified of the damage, dislocation, or disturbance?</b>	No

**Was the operator of the facility immediately notified of the damage, dislocation, or disturbance?**

Yes

**Was there an escape of any flammable, toxic, or corrosive gas or liquid?**

No

**Please provide a Fire Department or Emergency Services incident report, if available**

Not Available

**Attachment Information**

File names should not include symbols. Example:( \$, &, \*, %, . ) etc.