

South Dakota One Call Notification Board
PO Box 187
Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

Complaint filed on behalf of or by:	Montana Dakota Utilities
Contact Person:	Marcus Christensen
Phone	(605) 355-4035
Name or Company Name	Montana Dakota Utilities
Street Address or PO Box	PO Box 1060 Rapid City, South Dakota 57709 United States
Email	marcus.christensen@mdu.com
Date	Oct 22, 2020
Name of excavator / facility operator:	YANCY GRANGAARD
Phone	(605) 886-0559
Name or Company Name	GRANGAARD CONSTRUCTION
Street Address or PO Box	705 20TH AVE SW Watertown, South Dakota 57201 United States
Email	qcinc@wat.midco.net
Is this party aware of your allegations?	No

ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:
49-7A-8. Location of underground facilities--Marking.

An operator shall, upon receipt of the notice, advise the excavator of the location of underground facilities in the proposed excavation area by marking the location of the facilities with stakes, flags, paint, or other clearly identifiable marking within eighteen inches horizontally from the exterior sides of the underground facilities. The board shall promulgate rules, pursuant to chapter 1-26, to establish the response time for operators to mark the underground facilities. The response time shall be no later than forty-eight hours after the receipt of the notice, excluding Saturdays, Sundays, and legal holidays of the state or the excavation start time provided by the excavator, whichever is later. The response time may be less than forty-eight hours for emergency or subsequent inquiries to the original locate request and may be longer than forty-eight hours for nonexcavation requests. Excavators shall maintain a minimum horizontal clearance of eighteen inches between a marked underground facility and the cutting edge of any mechanical equipment. If excavation is required within eighteen inches,

horizontally, the excavator shall expose the facility with hand tools or noninvasive methods approved pursuant to rule and shall protect and support the facility prior to further excavation with mechanical equipment.

Other information to support your position:

Contractor was doing some digging in there construction site when they hit a 4 inch gas main. Contractor had a locate ticket and in the locate ticket and the comments were as follows "CALLER STATES NO NEED TO MARK - REPLICATION OF : 2026205159 WORK WILL BE DONE WITHIN A 300 FT RADIUS AROUND THE CENTER POINT OF THE BRIDGE." Marks had been destroyed by construction. Gas was blowing, 811 and 911 were both notified.

Street Address / location of alleged violation: Whitewood Valley Rd

City Whitewood

State South Dakota

Date of alleged violation: Oct 13, 2020

Time of alleged violation: 12:00 PM

Describe your allegation:

Contractor was digging and should have had marks refreshed to remind them of what utilities are in the area instead of say no need to mark. This may have prevented the damage.

Do you believe the alleged violation to be intentional? No

Was a locate requested from SD One Call? Yes

Locate ticket #: 2028219357

Start date on ticket: Oct 13, 2020

Start time on ticket: 09:00 AM

Did the excavator wait until the start date / time on the ticket before commencing excavation? Yes

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment? No

Explain

Contractor hit 4in gas main with there equipment

Were buried facilities exposed by hand or non- No

invasive equipment prior to excavation?

Were facilities marked?	No
Was the marking complete prior to the start time on the ticket?	NA
Did the excavator pre-mark with white paint?	No
Was the facility marked accurately (within 18 inches)?	NA
Did the excavator use reasonable care to maintain locate marks for the life of project?	No
Type of facility involved:	4" (P) Gas Main
Operator of facility (if known):	Montana Dakota Utilities
Operator address (Street or PO Box):	PO Box 1060 Rapid City, South Dakota 57709 United States
Operator Phone	(605) 355-4035
Depth of Cover (If unsure put N/A)	~36"
Pressure: (If none, write none)	50psig
Voltage: (If none, write none)	none
# of cable pairs: (If none, write none)	none
Was the facility damaged?	Yes
If yes, provide detail and an estimate of damage:	4in gas main - \$1200
Were damages on public right of way or private property?	Public

Was anyone injured as a result of facility damage? No

Were there fatalities? No

Was operator service affected? Yes

If yes, provide detail (how many customers for how long):

76 Customers - 6 hours for some customer and up to 11 hours for other. By the time the main was repaired and all relights were complete this is the time frame that it took.

Was the one-call notification center immediately notified of the damage, dislocation, or disturbance? Yes

Was the operator of the facility immediately notified of the damage, dislocation, or disturbance? Yes

Was there an escape of any flammable, toxic, or corrosive gas or liquid? Yes and 911 was contacted by an Excavator

Please provide a Fire Department or Emergency Services incident report, if available Not Available

Attachment Information

File names should not include symbols. Example:(\$, &, *, %, .) etc.