



## INCIDENT INVESTIGATION #201718

---



30 Adams St, Deadwood, SD

### LOCATION DETAILS

**Event Date:** 10/28/2020 02:00 PM America/Denver

**Right-of-Way:** City Street

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 2.00" Gas

**Facility part of joint trench:** No

**Asphalt or concrete removed:** Yes

**Damage Surface Type and Depth:** Blacktop < 18"

**Arrival Date and Time:** 10/28/2020 03:28 PM America/Denver



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:** 4x5 times 2

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Robert

**Contractor Representative Phone Number:** (605) 580-0411

**Personnel On Site:** Robert, berry

**Vehicles/Equipment Being Used For Repairs:** , 2 backhoes and shovel

**Guards or Barricades On Site:** Yes

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** RCs Construction

**Contact:** Berry

**Contact Phone:** (605) 209-0499

**Type of Work:** Storm drain

**Damage Responder:** Jessica, Myers

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Evan

**Utility Contact Phone:** (605) 639-5970

**Utility Representative:** Todd

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Storm Drain

**Excavator downtime?** Yes

**Downtime hours:** No

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Facility Owner

**Work area white-lined:** No

**Ticket Number:** 2029025013

**Date Located:** 10/19/2020 11:03 AM America/Denver

**Located By:** Kenny

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:**

**Customers Affected (approx.):** 16

## ROOT CAUSE

**Root Cause:** Excavator dug prior to verifying marks by test-hole (pot-hole)

## COMMENTS

**Assessment Comments:** Locator was notified around 3:30 of gas damage that happened at 3pm. Gas was blowing. 911 was present with 3 fire trucks. Gas was shut off at 6:01pm. As of 7:00 gas line still had not been repaired. Will gather more information in the am. 8 mdu employees where present

# INCIDENT AND SURVEY COMPARISON PHOTOS

## SURVEY PHOTO




Date: 10/19/2020 11:00 AM  
America/Denver

Latitude: 44.371944

Longitude: -103.724167

Heading: 26 degrees

## INCIDENT COMPARISON PHOTO



Date: 10/28/2020 05:11 PM  
America/Denver

Latitude: 44.372040

Longitude: -103.724371

Heading: 135 degrees

## **NEW INCIDENT PHOTOS**



## INCIDENT INVESTIGATION #201718

---



30 Adams St, Deadwood, SD

### LOCATION DETAILS

**Event Date:** 10/28/2020 02:00 PM America/Denver

**Right-of-Way:** City Street

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 2.00" Gas

**Facility part of joint trench:** No

**Asphalt or concrete removed:** Yes

**Damage Surface Type and Depth:** Blacktop < 18"

**Arrival Date and Time:** 10/28/2020 03:28 PM America/Denver



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:** 4x5 times 2

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Robert

**Contractor Representative Phone Number:** (605) 580-0411

**Personnel On Site:** Robert, berry

**Vehicles/Equipment Being Used For Repairs:** , 2 backhoes and shovel

**Guards or Barricades On Site:** Yes

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** RCs Construction

**Contact:** Berry

**Contact Phone:** (605) 209-0499

**Type of Work:** Storm drain

**Damage Responder:** Jessica, Myers

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Evan

**Utility Contact Phone:** (605) 639-5970

**Utility Representative:** Todd

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No



## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Storm Drain

**Excavator downtime?** Yes

**Downtime hours:** No

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Facility Owner

**Work area white-lined:** No

**Ticket Number:** 2029025013

**Date Located:** 10/19/2020 11:03 AM America/Denver

**Located By:** Kenny

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:**

**Customers Affected (approx.):** 16

## ROOT CAUSE

**Root Cause:** Excavator dug prior to verifying marks by test-hole (pot-hole)

## COMMENTS

**Assessment Comments:** Locator was notified around 3:30 of gas damage that happened at 3pm. Gas was blowing. 911 was present with 3 fire trucks. Gas was shut off at 6:01pm. As of 7:00 gas line still had not been repaired. Will gather more information in the am. 8 mdu employees where present

# INCIDENT AND SURVEY COMPARISON PHOTOS

## SURVEY PHOTO




Date: 10/19/2020 11:00 AM  
America/Denver

Latitude: 44.371944

Longitude: -103.724167

Heading: 26 degrees

## INCIDENT COMPARISON PHOTO



Date: 10/28/2020 05:11 PM  
America/Denver

Latitude: 44.372040

Longitude: -103.724371

Heading: 135 degrees

## NEW INCIDENT PHOTOS