South Dakota One Call Notification Board PO Box 187 Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

Complaint filed on behalf of or by:	Montana Dakota Utilities
Contact Person:	Marcus Christensen
Phone	(605) 355-4035
Name or Company Name	Montana Dakota Utilities
Street Address or PO Box	PO Box 1060 Rapid City, South Dakota 57709 United States
Email	marcus.christensen@mdu.com
Date	Dec 09, 2020
Name of excavator / facility operator:	Ross Jones
Phone	(605) 381-1195
Name or Company Name	Jones Construction Co.
Street Address or PO Box	5539 wildwood Dr Rapid City, South Dakota 57702 United States
Email	RJONESCO@RAP.MIDCO.NET
Is this party aware of your allegations?	No

ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED:

49-7A-5. Notification of proposed excavation.

No excavator may begin any excavation without first notifying the one-call notification center of the proposed excavation. The excavator shall give notice by telephone or by other methods approved by the board pursuant to rules promulgated pursuant to chapter 1-26 to the one-call notification center at least forty-eight hours prior to the commencement of the excavation, excluding Saturdays, Sundays, and legal holidays of the state. The board may promulgate rules to reduce the forty-eight-hour interval for emergency or subsequent inquiries to the original locate request and may lengthen the forty-eight-hour interval for nonexcavation requests.

Other information to support your position:

Contractor was working on installing a egress window when they hit the service line to the home. Line was located on a previous locate ticket from another contractor. Contractor did have a locate in there name at the address where the damage happened. Gas was blowing. 811 and 911 were notified.

Street Address / location of alleged violation:	5630 Bing
City	Rapid City
State	South Dakota
Date of alleged violation:	Dec 03, 2020
Time of alleged violation:	09:45 AM
Describe your allegation: No locate ticket requested in the contractor r	name.
Do you believe the alleged violation to be intentional?	No
Was a locate requested from SD One Call?	No
Did the excavator wait until the start date / time on the ticket before commencing excavation?	No
Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?	No
Were buried facilities exposed by hand or non- invasive equipment prior to excavation?	No
Were facilities marked?	Yes
Was the marking complete prior to the start time on the ticket?	ΝΑ
Did the excavator pre-mark with white paint?	ΝΑ
Was the facility marked accurately (within 18 inches)?	Yes

Did the excavator use reasonable care to maintain locate marks for the life of project?	ΝΑ	
Type of facility involved:	3/4" (P) Gas Line	
Operator of facility (if known):	Montana Dakota Utilities	
Operator address (Street or PO Box):	PO Box 1060 Rapid City, South Dakota 57709 United States	
Operator Phone	(605) 355-4035	
Depth of Cover (If unsure put N/A)	~18"-24"	
Pressure: (If none, write none)	50psig	
Voltage: (If none, write none)	none	
# of cable pairs: (If none, write none)	none	
Was the facility damaged?	Yes	
If yes, provide detail and an estimate of damage: 3/4" SL - \$500		
Were damages on public right of way or private property?	Private	
Was anyone injured as a result of facility damage?	No	
Were there fatalities?	No	
Was operator service affected?	Yes	
If yes, provide detail (how many customers for how long): 1 Customer - 1 hour		
Was the one-call notification center immediately notified of the	Yes	

damage, dislocation, or disturbance?	
Was the operator of the facility immediately notified of the damage, dislocation, or disturbance?	Yes
Was there an escape of any flammable, toxic, or corrosive gas or liquid?	Yes and 911 was contacted by an Excavator
Please provide a Fire Department or Emergency Services incident report, if available	Not Availiable
Attachment Information File names should not include symbols. Example:(\$, &, *, %.) etc.	